

Where ideas connect

Department of Environmental Quality Division of Water Quality

Michael O. Leavitt Governor Dianne R. Nielson, Ph.D. **Executive Director** Don A. Ostler, P.E. Director

288 North 1460 West P.O. Box 144870 Salt Lake City, Utah 84114-4870 (801) 538-6146 (801) 538-6016 Fax (801) 536-4414 T.D.D. www.deq.utah.gov

Please File to Water Quality Board William R. Chair Ray M. C.P.A. ce-Chair Robert Adams

David F. Echols

Heil K. Kochenour, M.D. Dianne R. Nielson, Ph.D.

Jay Ivan Olsen Joseph Piccolo, Mayor Ronald C. Sims, Ph.D. Douglas E. Thompson, Mayor J. Ann Wechsler Don A. Ostler, P.E. **Executive Secretary**

July 25, 2003

Jim Abegglen, Commissioner **Uintah County Commission** 152 East 100 North Vernal, UT 84078

Dear Commission Abegglen:

Subject:

Reconnaissance Inspection, Uintah County Asphalt Plant, Asphalt Ridge

We enjoyed meeting with you for a reconnaissance inspection at the Uintah County Asphalt Plant at Asphalt Ridge on July 23, 2003. A copy of the inspection report is enclosed.

If you have any questions concerning the report do not hesitate to contact Tom Rushing at (801) 538-6951. Thank you.

Sincerely,

Gayle Smith, P.E., Manager Permits and Compliance Section

ache butte

Enclosures: (1)

cc:

Darcy O'Connor, EPA Region VIII, (w/encl.)

Joseph B. Shaffer, M.A., M.B.A., E.H.S., Director of Health, Tricounty Health Dept., (w/encl.) Paul Baker, Senior Reclamation Biologist, Utah Division of Oil, Gas and Mining, (w/encl.)

> RECEIVED JUL 3 1 2003

DIV. OF OIL, GAS & MINING

United States Environmental Protection Agency Washington, D. C. 20460

NPDES Compliance Inspection Report

Form Approved OMB No. 2040-0003 Approval Expires 7-31-85

				Secti	On Al Hallona	I Data C	ystem	Coding			
	Transaction Code		NPDES			Yr/	Mo/Day	ln:	spection Type		spector Fac Type
1	N 2 5 3 N C	DIIP	E R M I T	1	11 12	0131	0 7 2	15] 17 18	3 [W]	19	20 <u> SIC</u> 2951
					Re	marks					
21		11	11111	111	шш	Ш	Ш	ШШ			66
	Reserved Facility Ev	aluatio	n Rating		BI		(QA		-Rese	ved
67	70 📙				71 📙		72]	73 📙	1	75	5
					Section B:	: Facilit	y Data	•			
Name and Location of Facility Inspected UINTAH COUNTY ASPHALT PLANT, ASPHALT RIDGE, VERNAL, UTAH					Entry Time					Permit Effective Date	
					H		1:00 P.M.			NO PERMIT	
								Exit Time/Date			Permit Expiration Date
N.				-				2:00 P.M./JULY	23, 2003		NO PERMIT
Name(s) of On-Site Representative(s) JIM ABEGGLEN PAUL FELTCH					Title(s)					Phone No(s) (435) 781-5380 (435) 789-1070	
					UINTAH COUNTY COMMISSIONER UINTAH COUNTY ROAD SUPERINTENDANT						
J1				11"							
m	e, Address of Responsible Official			- 1	Title(s)			age of the			
					UINTAH COL	JNTY C	OMMIS	SIONER			
JIM ABEGGLEN 152 EAST 100 NORTH VERNAL, UT 84078					. giř						
					Phone No.						Contacted
					(435) 781-538	30	1.5		- 2	-010	YES
			(S = Satisfa	Section	C: Areas Eva	luated I	During	Inspection ry, N = Not Evalua	ated)		工 编制 生
Permit N Flow Measurement								reatment N		N	Operations & Maintenance
	Records/Reports	N	Laboratory			N	Com	oliance Schedules		N	Sludge Disposal
	Facility Site Review	N	Effluent/Rece	iving Wa	/ater N		Self-Monitoring Program		N	Other:	
188		Sec	tion D: Summa	ry of Fi	ndings/Comm	ents (A	ttach a	dditional sheets	if necessary)		
am	e(s) and Signature(s) of Inspector(s)		The second secon	nencv/O	ffice/Telephone	e IBONMI	ENTAL	OLIAL ITY/DIVISIO	DN OF WATE		Date
am	e(s) and Signature(s) of Inspector(s) MAS RUSHING, ENVIRONMENTAL S	CIENT	IST DE	EPARTN JALITY	MENT OF ENV (801) 538-695	IRONM	ENTAL	QUALITY/DIVISIO	ON OF WATE	R	7-25-03
1C)	MAS FLUSHING, ENVIRONMENTAL S	CIENT	IST DE QU	JALITY Dency/O	MENT OF ENV (801) 538-695 ffice	IRONMI 51				R	
O Van	MAS RUSHING, ENVIRONMENTAL S ature of Reviewer LE SMITH, P.E., MANAGER		IST DE QU	DEPARTM UALITY Dency/O	MENT OF ENV (801) 538-695 ffice	IRONM		QUALITY/DIVISIO		R	7-25-03
lo /n	MAS FLUSHING, ENVIRONMENTAL S		IST DE QU	DEPARTM UALITY Dency/O	MENT OF ENV (801) 538-695 ffice MENT OF ENV (801) 538-677	IRONMI IRONMI 19	ENTAL	QUALITY/DIVISIO		R	7-25-03
TO Van	MAS RUSHING, ENVIRONMENTAL S ature of Reviewer LE SMITH, P.E., MANAGER		IST DE QU	DEPARTM UALITY Dency/O	MENT OF ENV (801) 538-695 ffice MENT OF ENV	IRONMI IRONMI 19	ENTAL	QUALITY/DIVISIO	ON OF WATE	R	7-25-03

UINTAH COUNTY ASPHALT PLANT, ASPHALT RIDGE RECONNAISSANCE INSPECTION

INSPECTION DATE JULY 23, 2003

PROJECT BACKGROUND INFORMATION

The Uintah County Asphalt Plant (plant) is located just outside of the City of Vernal in Uintah County, Utah (overview Fig 1.). The plant is located on land owned by Crown Energy (Facility Photo Fig 2.) and leased by Uintah County. Uintah County is actively mixing asphalt with gravel at the site, as per Federal and State regulations this is considered an asphalt manufacturing facility. The area has historically drained storm water in sheet and gully flow. When Crown Energy built their plant and the associated roads there was not an objective to maintain the natural drainage.

This inspection was prompted by a letter from LeBoeuf, Lamb, Greene & McRae, LLP (LLGM), addressed to Uintah County and Carbon Copied to the Utah Department of Environmental Quality. LLGM was contracted by "The Haws Family Trust" to incite action against Uintah County for alleged violations of the Clean Water Act and for personal property damage. "The Haws Family Trust" owns the land below (down gradient of) the plant.

FINDINGS

- 1. The Uintah County Asphalt Plant at Asphalt Ridge falls under the Standard Industrial Classification No. 2951 and is considered an asphalt manufacturing facility.
- 2. Uintah County is required to obtain coverage under the Utah Pollutant Discharge Elimination System (UPDES) Multi-Sector General Permit for Industrial Activities, General Permit No. UTR00000. A separate letter was sent Uintah County on July 17, 2003 providing them with a copy of the permit and "Notice of Intent" form to be covered under the permit. The letter gives Uintah County 30 calendar days to obtain coverage under the permit in compliance with State rules and regulations from the date of receipt.
- 3. The area below the asphalt plant was visually inspected for evidence of asphalt material that was transported offsite by storm water. There was no evidence of transported material.
- 4. It was observed that there was a potential for the discharge of contaminated storm water from the site particularly from the front gate area. The option of containing potentially contaminated storm water in retention ponds onsite was discussed. Uintah County will consider putting together specifications for the construction of onsite retention ponds. Construction plans for wastewater retention ponds require review and approval by the Division of Water Quality.

CONCLUSION

Uintah County has agreed to put together a storm water pollution prevention plan and submit a notice of intent for coverage under UPDES permit no. UTR00000 within 30 days of the receipt of the letter sent by the Division of Water Quality on July 17, 2003.

Pictures - Uintah County Asphalt Plant (Asphalt Ridge), July, 23, 2003



Fig 1. View of asphalt facility.




Fig 2. View of Crown Energy above the asphalt plant. The asphalt plant property is leased by Uintah County from Crown Energy.



Fig 3. Culvert Pipe. This is the only constructed drain observed in the area. The drain receives runoff from the road in fig. 2 as well as other areas. Storm water is greatly concentrated to this area. Prior to construction of roadways, etc. the storm water likely flowed in a more disperse fashion. This is evidenced by multiple drainage areas on the property below.



Fig 4. Low area on south side of asphalt plant. It was mentioned during the inspection that the runoff from the asphalt piles could easily be made to flow to this area. Uintah County sees benefit to build a containment pond in this area to receive contaminated storm water runoff.




Fig 5. Low area on the north side of the asphalt plant. Uintah County sees a benefit in constructing a controlled containment system in this area to receive runoff from the north facility area. The containment would be for contaminated runoff.




Fig 6. Berm. The west apron of the asphalt facility has been bermed. Asphalt mixing/manufacturing can be seen on the right side of the picture.